

NABCO ENTRANCES TECHNICAL BULLETIN

S82 W18717 Gemini Drive
Muskego, WI, 53150
Phone: (877) 622-2694, Fax: (888) 679-3319
www.NabcoEntrances.com

Date: 2/18/11

Who is the technical contact?
Alan Kettering


**Change to the Location of Rocker Switches on 1175 Sliding Doors
(National Accounts only)**

Effective immediately, all GT-1175 Sliding Door Systems that are supplied on Nabco National Account projects will have the rocker switch located on the face of the jamb tube as shown below. The rocker switch will not be located on the sidelite panel as is currently done on standard sliders.

Switches will be installed on the inside jamb face on the same side of the frame that the control and operator is located. On full open sliders this is typically the left side (see below) and on fixed sidelite sliders this is typically the right side as viewed from the interior.

We expect this change to also facilitate installation of the sidelites as well as eliminate damage to rocker switch wiring between the header and sidelite.

Interior Elevation (full open slider shown)



Bulletin Number: **48**