Technical Bulletin Technical Bulletin Technical Bulletin Technical Bulletin Technical Bulletin Technical Bulletin

NABCO ENTRANCES TECHNICAL BULLETIN

S82 W18717 Gemini Drive Muskego, WI, 53150 Phone: (877) 622-2694, Fax: (888) 679-3319 www.NabcoEntrances.com

, ,	
Who is the technical conta	art?
Technical Support Departr	

Date: January 20, 2017

Using "Push & Go" on GT20

Issue:

When "Push & Go" is being used, the GT20 will apply breaking if the door is pushed manually faster than the programmed opening speed. In some cases, this may not be desirable.

Reason:

The GT20, during normal operation, is designed to maintain a constant opening speed (dependent on the opening speed setting, "Vo"). If the wind catches the door, forcing it to open excessively fast, braking is applied to help prevent damage.

Solution:

Increasing opening speed (Vo) can help with this, <u>as long as the door does not open faster than ANSI standards allow.</u>

The GT20's software is being evaluated to find an ideal solution that balances ease of manual opening and protection from wind. Once a solution becomes available, another bulletin will be released. Since the GT20 can be updated in the field using a USB memory device, new software will be provided upon request.

Bulletin Number: **80**

Technical Bulletin Technical Bulletin Technical Bulletin Technical Bulletin Technical Bulletin Technical Bulletin