

S82 W18717 Gemini Drive Muskego, WI, 53150 Phone: (877) 622-2694, Fax: (888) 679-3319 www.NabcoEntrances.com

TECHNICAL BULLETIN

Date: Jan 24, 2017

Who is the contact?
Technical Support Department

Opus Control Programming Tips Update

The following is a correction to Technical Bulletin 77 (item 9).

On a double egress doors, safety sensors should always be **connected** to the control that operates the door which that sensor is covering. It is best to NOT parallel safety signals between controls regardless of other wiring or software revision.

Additional tip:

Using Push-to-Go On all controls up to and including rev. B20

- 1. When using the on/off/hold-open switch (4 wire type), after a door has been turned off, then back on, push-to-go will not resume working unless a signal is presented to an activation input, or power is cycled. Software rev. B21 does not have this problem.
- 2. Field fix:
 - A) wiring: The blue wire from the on/off/hold-open switch should be removed from terminal 8, and placed into terminal 4.
 - B) programming: under "input settings"; set "input 62" to "Emergency Close" set "input 62 circuit" to "normally closed" set "input BA circuit" to "normally open".
 - C) if a separate external activation is needed, input H (terminal 10) can be set to "external activation", also under "input settings".

Bulletin Number: **81**