

# NABCO ENTRANCES TECHNICAL BULLETIN


S82 W18717 Gemini Drive  
Muskego, WI, 53150  
Phone: (877) 622-2694, Fax: (888) 679-3319  
www.NabcoEntrances.com

Date: 9/4/14

Who is the technical contact?  
Mike Buckley


## Handy Terminal Harness to be Eliminated from New GT 1175 Headers

Starting Oct. 1, 2014 Handy Terminal Harness (P/N 14-11837) as shown below will no longer be installed in GT1175 slider headers. Therefore, to program the U30 control, technicians will need to have both the Harness plus the Handy Terminal in their possession.




This end of Harness  
P/N 14-11837  
connects to Handy  
Terminal cord

This end of Harness  
P/N 14-11837  
plugs into U30 control



Handy Terminal Harness (P/N 14-11837)



To ease the change over, during this month of September, new harnesses for each of your technicians can be ordered free of charge from Nabco Customer Service by authorized distributors who request them. These harnesses should be distributed to your technicians who should retain them as a programming accessory with their Handy Terminal.

After October 1st, these harnesses will continue to be available for purchase as a separate item under P/N 14-11837 or as part of a new assembly which includes the Harness plus the Handy Terminal. This new assembly P/N is 14-14804.

To facilitate the change, please ensure you order Harness P/N 14-11837 for your technicians before the end of the month.

Bulletin Number: **63**