Technical Bulletin Technical Bul

NABCO ENTRANCES TECHNICAL BULLETIN

S82 W18717 Gemini Drive Muskego, WI, 53150

Phone: (877) 622-2694, Fax: (888) 679-3319

www.NabcoEntrances.com

Date: 4/2/15

Who is the technical contact?

Alan Kettering

Factory Installed Holding Beams

Holding beams on all 1175's will be factory installed. This includes beams used for breakout. The only thing left to do is to connect the beams to their corresponding wires coming out of the header.

Wires for breakout beams will be identified as such.

The beam lenses are covered with foam to protect them during the installation process.

Do not remove the protection until installation is complete and the control is ready for programming. If protection isn't in place, we recommend adding some for installation.



Replacement parts:

Optex OS-12C Beam Control, P.N. A-00129



Beams with extension wires, (1 emitter, 1 detector) P.N. V-00073



Bulletin Number: **66**

15-9537-xx Technical Bulletin Technical Bulletin Technical Bulletin Technical Bulletin Technical Bulletin Technical Bulletin