Technical Bulletin Technical Bulletin Technical Bulletin Technical Bulletin Technical Bulletin Technical Bulletin Technical Bulletin

NABCO ENTRANCES TECHNICAL BULLETIN

S82 W18717 Gemini Drive Muskego, WI, 53150 Phone: (877) 622-2694, Fax: (888) 679-3319

www.NabcoEntrances.com

| Who is the technical contact? Mike Buckley |
|---|

Date: 9/17/15

— REMINDER —

Handy Terminal Harness Has Been Eliminated From GT 1175 Headers

Refer to the Bulletin 63 on the following page. This bulletin was sent out to all distributors on September 4, 2014

Apparently some of our distributors are not aware that we no longer send this cable with sliders.

- Please pass this information along to your dealers also. 1
- 2. Please make copies of this bulletin and pass it out to all of your technicians.
- If technicians want cables you can order them. The part number of the 3. cable is: M-01517 (old part number 14-11837)
- A cable should be kept with each Handy Terminal. 4.

Bulletin Number: 63 A

Technical Bulletin Technical Bulletin Technical Bulletin Technical Bulletin Technical Bulletin Technical Bulletin Technical Bulletin



Technical Bulletin

Technical Bulletin

Technical Bulletin

Technical Bulletin Technical Bulletin

Technical Bulletin

NABCO ENTRANCES TECHNICAL BULLETIN

S82 W18717 Gemini Drive Muskego, WI, 53150

Phone: (877) 622-2694, Fax: (888) 679-3319

www.NabcoEntrances.com


Date: 9/4/14

Who is the technical contact?

Mike Buckley


Handy Terminal Harness to be Eliminated from New GT 1175 Headers

Starting Oct. 1, 2014 Handy Terminal Harness (P/N 14-11837) as shown below will no longer be installed in GT1175 slider headers. This harness runs between the U30 control and the end of the header and provides a connection point for the Handy Terminal cable.




This end of Harness P/N 14-11837 connects to Handy Terminal cable

This end of Harness P/N 14-11837 plugs into U30 control



Handy Terminal Harness (P/N 14-11837)



Therefore, to program the U30 control, technicians will need to have both the Harness plus the Handy Terminal in their possession.

To ease the change over, during this month of September, new harnesses for each of your technicians can be ordered free of charge from Nabco Customer Service by authorized distributors who request them. You must supply Customer Service with information on how many technicians you have on staff. These harnesses should be distributed to your technicians who should retain them as part of their Handy Terminal assembly.

After October 1st, these harnesses will continue to be available for purchase as a separate item under P/N 14-11837 or as part of a new assembly which includes the Harness plus the Handy Terminal. This new assembly P/N is 14-14804.

To facilitate the change, please ensure you order Harness P/N 14-11837 for each of your technicians before the end of the month.

Bulletin Number: **63**

Technical Bulletin Technical Bulletin Technical Bulletin Technical Bulletin Technical Bulletin Technical Bulletin Technical Bulletin